

Work Order ID 76938

76938

Page 1

November-24-11 10:14:58 AM

Item ID: D3161-7 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Hinge 14.0" **11**
 Start Date: 24/11/2011 Start Qty: ~~10.00~~ ***10*** Cust Item ID:
 Required Date: 28/11/2011 Req'd Qty: 10.00 ***10*** Customer:
 Reference:

Approvals: Process Plan: M.C.J Date: 11/11/24 Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3161	Rev A2

100	Small Fab	0.00							
100									
Small Fab	Memo	0.00							
Small Fab	(1) 72" Hinge makes (5) D3161-7 parts at 14" longCut to length as per Dwg D3161								

EP 11/11/28 (11)

110	QC5- Inspect part completeness to step on W/O	0.00							
110									
QC	Memo	0.00							
Quality Control									

SB alal-29 (11)

120	Identify as per dwg & Stock Location: <u>ST</u>	0.00							
120									
Packaging	Memo	0.00							
Packaging									

EP 11/11/28 (11)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 76938***76938***

Page 2

November-24-11 10:14:58 AM

Item ID: D3161-7 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Hinge 14.0"
Start Date: 24/11/2011 Start Qty: 10.00 ***10*** Cust Item ID:
Required Date: 28/11/2011 Req'd Qty: 10.00 ***10*** Customer:
Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130	QC21- Final Inspection - Work Order Release	0.00							
130									
QC	Memo	0.00							
Quality Control									

11/11/28 *[Signature]*
MF
11-11-28

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

November-24-11 10:15:01 AM

Page 1

Work Order ID: 76938

76938

Parent Item: D3161-7

D3161-7

Parent Item Name: Hinge 14.0"

Start Date: 24/11/2011

Required Date: 28/11/2011

Start Qty: 10.00

Required Qty: 10.00

Comments: IPP A04.08.24New IssueKJ/JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MS20257-3-7200		Purchased	No			100	f	62.5764	1.2	12			
MS20257-3-7200									**				
Piano Hinge													

Location

Loc Qty

Loc Code

ST449

0.00778948

116817

0.00778948

ST489A

62.56864

117543

2.126

118686

0.44264

119638

60

EB 11/28
13.2

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries



DESIGN #	DRAWN BY #	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED KF	APPROVED #	DRAWING NO. D3161	REV. A SHEET 1 OF 1
DATE 02.04.24		TITLE HINGE	SCALE NTS
A	02.04.24	NEW ISSUE	
A1	04.02.27	ADDED D3161-5	
A2	04.06.30	ADD D3161-7 & D3161-9	

RELEASED
02.04.24 #

P/N	LENGTH 'L'	DESCRIPTION
D3161-1	13.5"	HINGE (REPLACES MS20257-3-13.5 ON D2183)
D3161-3	15.0"	HINGE (REPLACES MS20257-3-15.0 ON D2950-041)
D3161-5	9.9"	HINGE
D3161-7	14.0"	HINGE
D3161-9	17.0"	HINGE



SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
76939 M.C.O
n/n/24

NOTES:

- ① MAKE FROM MS20257-3-7200 HINGE

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries